

Restoration of the Gen. U. S. Grant Birthplace in Pt. Pleasant, Ohio



After restoration, including power washing, wood siding and trim repair, window reglazing, bare wood priming, and repainting.



Before restoration, showing peeling paint on siding, railings, doors, and chimney.